



After SVI Refurb



Rock Springs, WY Fire Department Pumper Refurb



Highlights

Front Brake Replacement LED Cab Interior Lighting Upgrade Tank Level Gauge LED Readout Replacement Powered and Heated Side Mirrors Addition New Interior Stainless-Steel Door Panel Fabrication Gold Leaf Engine Number Graphics Diamond Plate Aluminum Hose Bed Cover Installation Curbside Lower Compartment Doors Fabrication Spotlight, Headlight and Tailgate LED Upgrade

Rock Springs, WY Fire Department Pumper Complete Refurb Details

BODY

- Rear compartment rust repair
- Cab/chassis undercarriage cleaning and undercoat application
- Interior stainless-steel door panel fabrication
- Latch, closures and weather stripping replacement on rear compartment doors and cab interior doors/panels
- Curbside lower compartment doors out of tread plate fabrication

ENGINE & CHASSIS

- In-frame engine overhaul
- Transmission overhaul
- Front brake replacement
- Odometer gauge replacement
- Corroded battery box replacement

LIGHTING

- Cab interior lighting LED upgrade
- Tank level gauge replacement with LED readout
- Headlight and tailight LED upgrade
- Rear lower LED warning lights addition
- Spotlight LED upgrade
- Step light repair
- Front spotlight repair
- Rear tailboard marker lights repair (secured using silicone)

PUMP

- Pump plumbing and linkage inspection
- Pump test
- Intake and discharge valve rebuild
- Pump panel light LED upgrade
- Water pump front and back seal replacement

PAINT & GRAPHICS

• Gold leaf engine number graphics upgrade (changed to match Rock Springs existing fleet graphics)

UPGRADES / OTHER

- Setcom headset installation with driver wireless set
- Powered and heated side mirrors upgrade
- Diamond plate aluminum hose bed cover fabrication and installation
- Center console map box fabrication and installation
- 12-volt USB charge block installation (inside cab)
- Air system inspection