



After **SVI Refurb**



## Rock Springs, WY Fire Department Pumper Refurb

Before



### Highlights

- Front Brake Replacement
- LED Cab Interior Lighting Upgrade
- Tank Level Gauge LED Readout Replacement
- Powered and Heated Side Mirrors Addition
- New Interior Stainless-Steel Door Panel Fabrication
- Gold Leaf Engine Number Graphics
- Diamond Plate Aluminum Hose Bed Cover Installation
- Curbside Lower Compartment Doors Fabrication
- Spotlight, Headlight and Tailgate LED Upgrade

# Rock Springs Pumper

## Refurb Specs

### BODY

- Repair rear compartment rust
- Apply cab/chassis undercarriage cleaning and undercoat
- Fabricate interior stainless-steel door panel
- Replace latch, closures and weather stripping on rear compartment doors and cab interior doors/panels
- Fabricate curbside lower compartment doors out of tread plate

### ENGINE & CHASSIS

- Overhaul in-frame engine
- Overhaul transmission
- Replace front brake
- Replace odometer gauge
- Replace corroded battery box

### LIGHTING

- Upgrade cab interior lighting LED
- Replace tank level gauge with LED readout
- Upgrade headlight and taillight LED
- Add rear lower LED warning lights
- Upgrade spotlight LED
- Repair step light
- Repair front spotlight
- Repair rear tailboard marker lights (secured using silicone)

### PUMP

- Provide pump plumbing and linkage inspection
- Provide pump test
- Rebuild intake and discharge valve
- Upgrade pump panel light LED
- Relace water pump front and back seal

### PAINT & GRAPHICS

- Print and install gold leaf engine number graphics (changed to match Rock Springs existing fleet graphics)

### UPGRADES / OTHER

- Install Setcom headset installation with driver wireless set
- Install powered and heated side mirrors
- Fabricate and install diamond plate aluminum hose bed cover fabrication
- Fabricate and install center console map box
- Install 12-volt USB charge block (inside cab)
- Inspect air system