



After **SVI Refurb**



Grand County Aerial Refurb

Existing Chassis

Pierce Arrow XT

Before



Refurbishment Details

- Partial Paint (Top Half Painted White to Match Fleet)
- New Signage and Lettering to Match Fleet
- Loose Latch Repair on Ladder Bucket Door
- Bent Rear Bumper Repair
- Made New Sign Boards
- Radio Installation

Grand Fire Protection District CO Aerial

Complete Refurb Details

BODY

- Prep sand and mast complete truck
- Refinish and buff truck body
- Paint top half white
- Fabricated new sign boards

GRAPHICS

- Changed signage and lettering to match current trucks

REPAIRS

- Fixed loose latch on ladder bucket door
- Fixed bent rear bumper corner

UPGRADES

- Installed radio